






A view



measurement tolerance							
tolerance	X. XX	X. X	X.				
0-25	±0.05	±0.10	±0.15				
25-100	±0.10	±0.15	±0.20				
100-250	±0.15	±0.20	±0.25				
250-500	±0.20	±0.30	±0.50				
500-750	±0.30	±0.50	±0.75				
750-	±0.45	±0.65	±1				
				view	